Approved For Release 2008/03/31 : CIA-RDP78B04558A000500040019-3

SECRET

Declassification Review by NGA/DoD

OUT56763

24 SEP 1965

COPIES RECEIVED 1

Cy No.	Office	Act.
	File	
2	OS	
	ADMIN	
	SEC BR	
	P&DS	
	C&D	
	IPD	
	PD	
	MAXX 4	
	SPOD	
	NSA-LO	
	DIA-AP	

25X1

S E C R E T 232236Z

1965 SEP 23 22 47Z

1. CAMERA B 23 WAS USED IN MISSION 8045 FLOWN ON 21 SEPTEMBER 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND RESOLUTION IS GOOD WHERE NOT DEGRADED BY WEATHER CONDITIONS.

B. 9R SIDE: A NUMBER OF SHORT IRREGULAR PLUS DENSITY STREAKS ARE PRESENT AT RANDOM IN FRAMES 001 TO 240. FRAMES 721 TO 980 CONTAIN A CONTINUOUS IRREGULAR PLUS DENSITY STREAK WITHIN 3.0" OF THE OUTBOARD EDGE. INTERMITTENT LINEAR PLUS DENSITY STREAKS ARE PRESENT ON THE INBOARD EDGE OF FRAMES 873 TO 980. PINHOLES ARE NOTED INTERMITTENTLY THROUGHOUT THE MATERIAL. MANUFACTURER'S SPLICES ARE PRESENT IN FRAMES 556 AND 1952. FRAME 1031 CONTAINS A BREAKDOWN SPLICE. A HEAVY SCRATCH DEGRADES FRAME 721. FRAME 733 CONTAINS A BLISTER AND EMULSION LIFTS ARE NOTED IN A CORRESPONDING LOCATION IN FRAMES 734 AND 735.

C. 9L SIDE: A MINUS DENSITY STREAK 1.4" FROM THE INBOARD EDGE IS PRESENT ON FRAMES 0001 TO 1041. THE MINUS DENSITY STREAK ENDS AT THE BREAKDOWN SPLICE WHICH WAS MADE THROUGH THE MANUFACTURER'S SPLICE ON FRAME 1041. HANDLING MARKS AND EMULSION LIFTS ASSOCIATED WITH THE SPLICES ARE ON FRAMES 1041 TO 1043. FOG DUE TO LIGHT LEAKS ARE PRESENT PERPENDICULAR TO THE MAJOR AXIS AND LOCATED ON FRAMES 1, 2, 2147 AND 2149. EMULSION LIFTS ARE PRESENT INTERMITTENTLY THROUGHOUT THE MISSION. SEE FRAMES 950, 1040 AND 1392 AS AN EXAMPLE.

SECRET

Approved For Release 2008/03/31 : CIA-RDP78B04558A000500040019-3

Approved For Release 2008/03/31 : CIA-RDP78B04558A000500040019-3

MINUS DENSITY COMETS ARE PRESENT ON FRAMES 219 AND 1096. TITLE FLAKING OCCURRED ON EACH EVEN NUMBERED FRAME OF PARTS 2 AND 3 WHICH MADE THE MISSION NUMBER DIFFICULT TO READ AT TIMES.

D. BOTH SIDES: EDGE STATIC AND ROLLER CHATTER ARE PRESENT ON BOTH EDGES THROUGHOUT THE MISSION. THE DATA CHAMBER IS MISSING ON FRAME 1. THE LAST TITLED FRAME OF THE MISSION IS 2149.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING IS GOOD.

C. CLOUDS COVERED APPROXIMATELY 25 PERCENT OF THE MISSION.

S E C R E T

--END OF MESSAGE--

Approved For Release 2008/03/31 : CIA-RDP78B04558A000500040019-3